

1 **Wind Performance Assessment of Post-Disaster Housing in the Philippines**

2 Casie Venable^{1*}, Abbie B. Liel², Tracy Kijewski-Correa³, Amy Javernick-Will⁴

5 ¹*Ph.D. Candidate, Dept. of Civil, Environmental and Architectural Engineering, Univ. of Colorado*
6 *Boulder, Boulder, CO 80309. Email: [casie.venable@colorado.edu](mailto:cacie.venable@colorado.edu)*

8 ²*Associate Professor, Dept. of Civil, Environmental and Architectural Engineering, Univ. of Colorado*
9 *Boulder, Boulder CO 80309. Email: abbie.liel@colorado.edu*

10 ³*Associate Professor, Dept. of Civil & Environmental Engineering & Earth Sciences and Keough School*
11 *of Global Affairs, Univ. of Notre Dame, Notre Dame, IN 46556. Email: tkijewsk@nd.edu*

14 ⁴*Associate Professor, Dept. of Civil, Environmental and Architectural Engineering, Univ. of Colorado*
15 *Boulder, Boulder CO 80309. Email: amy.javernick@colorado.edu*

17 *Corresponding Author

18 **Abstract**

19 Although organizations build housing after typhoons and other disasters in resource-limited
20 contexts that is intended to be safer than what existed previously, the performance of these houses
21 in future typhoons—and the factors influencing performance—are unknown. This study develops
22 a component-level, performance-based wind engineering assessment framework and evaluates the
23 wind performance of twelve semi-engineered post-disaster housing designs, representing
24 thousands of houses that were constructed in the Philippines after Typhoon Yolanda. We found
25 that roof panel loss likely occurs first for most designs, at wind speeds equivalent to a category 2
26 hurricane/signal 3 typhoon. Roof shape determines whether this loss is caused by failure at the
27 panel-fastener interface or purlin-to-truss connection. However, houses with wooden frames and
28 woven bamboo walls may also experience racking failures at wind speeds equivalent to signal 2
29 or 3 typhoons, a situation exacerbated by strengthening the roof. Results also show that wind
30 performance varied with roof shape, component spacing, panel thickness, eave length and
31 connection between purlin and truss. Organizations can use these results to improve housing
32 performance, taking specific care to increase wall capacity and ensure a continuous load path. This
33 framework can be expanded to assess housing performance in other resource-limited contexts.

34 **Keywords**

35 Post-disaster housing, Housing performance, Wind assessment, Typhoons, Typhoon Yolanda

36 **Introduction**

37 Tropical cyclones (known as hurricanes in the Atlantic, and referred to here as typhoons) cause billions of
38 dollars of damage and destroy thousands of houses each year, particularly in resource-limited communities
39 (CRED and UNISDR 2018; Rentschler 2013). In these communities, most households do not have
40 sufficient capital to reconstruct their house without assistance, so organizations provide housing
41 reconstruction assistance, with the goal that the new houses can better withstand future hazards (Clinton
42 2006; Twigg 2017). If a house is provided, organizations will often use a single standardized design that is
43 built many times in one or more communities (Da Silva and Batchelor 2010). At best, these designs are
44 semi-engineered by architects and engineers, but in some cases, little to no engineering calculations are
45 used, and the expected performance of these houses in future disasters is unknown (Harriss et al. 2020).
46 Given their limited resources, organizations must make the decision whether to provide more households
47 with a cheaper house or fewer households with a more expensive house (Schilderman 2010). Moreover,
48 households who do not receive assistance in rebuilding their homes are likely to observe the houses that
49 organizations built and attempt to implement similar designs (Turnbull et al. 2015). Organizations must
50 therefore find low-cost, locally sourced, culturally acceptable, and hazard-resilient solutions for the houses
51 they build and the houses that will imitate their designs (Kijewski-Correa et al. 2012). Because there is not
52 a current framework for assessing post-disaster housing and little is known about either the performance of
53 these post-disaster houses or the effect of design decisions on performance, there is a need for both an
54 assessment framework and an evaluation of how constructed houses are expected to perform.

55 In this study, we develop a component-level performance-based wind engineering assessment
56 framework to: 1) assess houses constructed in resource-limited communities by organizations after
57 disasters, and 2) evaluate how various design changes can improve performance. Performance-based wind
58 engineering assessments, which exist for differently-designed houses in other contexts but not post-disaster
59 housing in resource-limited contexts, allow us to define a specific performance objective for a house in a
60 future typhoon, and probabilistically assess the likelihood of meeting this objective, as well as the
61 consequences of failing to do so (Barbato et al. 2013; Ellingwood 2015). An improved understanding of

62 the typhoon performance of post-disaster housing constructed by nongovernmental organizations (NGOs)
63 and governments in resource-limited communities is specifically needed to identify the vulnerabilities in
64 common designs and to provide organizations with the information needed to improve the performance of
65 these houses. This study responds to this need, with application to twelve semi-engineered post-disaster
66 housing designs, representing thousands of houses that were constructed in the Philippines after Typhoon
67 Yolanda.

68 **Previous Assessments of Housing Wind Performance**

69 Below we summarize prior observations of post-disaster housing safety, assessments of North American
70 and Australian housing, and reconnaissance of wind damage to houses in resource-limited contexts.

71 ***Post-Disaster Housing***

72 Commonly, organization-assisted post-disaster housing follows a ‘core’ shelter design, meaning the house
73 is rectangular in shape, has few or no interior partitions, and has no more than three or four roof trusses.
74 Typical materials used in these houses include wood or reinforced concrete (RC) frames; masonry,
75 plywood, or woven walls; and corrugated galvanized iron (CGI) roof panels.

76 Despite the emphasis on building safer houses, there is little evidence to suggest whether post-
77 disaster housing is safer than pre-disaster designs. For example, Lyons (2009) assessed NGOs’ and
78 government agencies’ post-tsunami housing reconstruction in Sri Lanka and found that housing
79 vulnerabilities were recreated in the reconstruction due to use of poor-quality materials and a lack of
80 construction oversight. What we do know about the safety of post-disaster housing tends to come either
81 from implementing organizations’ reports or case studies conducted shortly after housing reconstruction
82 projects ended (Harriss et al. 2020; Schilderman 2014). These reports are limited in that they generally
83 provide information only about design features used to enhance safety, but not the long-term performance
84 of the houses (Peacock et al. 2007; Schilderman 2014). However, a few studies have examined the design
85 features in post-disaster housing using visual audits. In the Philippines, after 2013’s Typhoon Yolanda,
86 Opdyke et al. (2019) assessed housing safety in 19 post-disaster projects by observing whether a checklist
87 of design improvements (e.g., bracing and tie-downs) suggested by the Philippines Shelter Cluster (2014)

88 were present in housing designs, finding that 11 of the designs had incorporated at least 5 of the ‘8 Key
89 Messages’. Likewise, Stephenson et al. (2018) examined whether houses that were constructed by
90 households using cash and materials from NGOs in three communities after Yolanda had three features that
91 were expected to influence performance in typhoons (hip roofs, roof vents, and eaves no longer than 0.5
92 m). They found that a majority of houses had eaves longer than 0.5m and a gable roof, both of which can
93 increase vulnerability to wind damage.

94 While these quick visual audits provide useful information about the potential vulnerabilities of
95 post-disaster housing, they do not quantify the wind speed expected to cause damage or identify the specific
96 failure mode. Nor do they show the value or detriment of certain design decisions in terms of performance.
97 Detailed structural assessments can provide this information, but we could find no published studies that
98 analytically assessed the wind performance of post-disaster housing. We found two studies involving
99 experimental testing of post-disaster housing that included a series of tests on permanent houses designed
100 by the Tongan Ministry of Works transitional shelters designed by the United States Agency of International
101 Development (USAID). The tests of the Tongan house resulted in new design recommendations, including
102 new truss tie downs (Boughton and Reardon 1984), and the test of the USAID shelter found that this shelter
103 could not withstand wind speeds greater than 177 kph (110 mph), equivalent to a category 2 hurricane in
104 the U.S. (Liu-Marques et al. 2012). There is, thus, an urgent need for structural assessments of post-disaster
105 housing using component-based analyses, with demands and capacities quantified by prescriptive codes
106 and values published in the literature and uncertainty propagated using a Monte Carlo approach.

107 ***Housing in North America and Australia***

108 A significantly greater number of studies have examined the wind performance of timber housing in North
109 America and Australia (e.g., Ellingwood et al. 2004; Gavanski and Kopp 2017; Henderson et al. 2013a; b;
110 Morrison et al. 2012; Unnikrishnan and Barbato 2017). However, the houses examined in these studies
111 differ from the housing built in resource-limited communities in that they are larger, with more complex
112 floor plans, different types of timber, superior framing and connections, and more redundant roof systems.
113 In addition, North American houses typically have oriented strand board or plywood roof sheathing;

114 although, Australian houses commonly use metal roof cladding that is similar to the CGI often used in post-
115 disaster housing.

116 Nevertheless, these previous studies highlight methodologies that can be used to assess the
117 performance of post-disaster housing. For instance, Ellingwood et al. (2004) and Lee and Rosowsky (2005)
118 proposed methods for assessing wind damage fragilities for different roof components. These fragilities
119 define the likelihood of damage to these components as a function of wind speed. In addition, Li and
120 Ellingwood (2006) illustrated how to incorporate uncertainty into a performance-based wind assessment.
121 Studies of houses in Australia have further demonstrated component-based performance-based wind
122 engineering approaches to assessing housing vulnerability (Henderson and Ginger 2007; Stewart et al.
123 2018). These assess the vulnerability of individual components (*e.g.*, walls or roofs) in a given design, and
124 relate the structure's overall vulnerability to the vulnerabilities of its constitutive components (Goyal et al.
125 2012). For example, Henderson and Ginger (2007) proposed a series of failure mechanisms for components
126 found in a typical Australian house with metal roof cladding and related these component failure
127 mechanisms to global limit states of interest.

128 ***Previous Reconnaissance of Typhoon Damage to Houses***

129 There are also studies that have documented typhoon-related housing damage in resource-limited
130 communities. Common types of damage are loss of roof cladding (Prevatt et al. 2010; Shanmugasundaram
131 et al. 2000), global roof system loss due to the failure of the connections between the roof trusses and walls
132 (Mukhopadhyay and Dutta 2012), wall failures (Build Change 2014; Kijewski-Correa et al. 2017), and in
133 extreme cases, overturning due to the lack of adequate foundations (Mukhopadhyay and Dutta 2012). Some
134 of these failures have been documented in NGO-constructed houses (Kijewski-Correa et al. 2017). Each of
135 these failure mechanisms can endanger occupant safety: for example, loss of roof cladding exposes
136 occupants to the elements and loose cladding can become a wind-borne debris hazard; roof system loss and
137 wall racking, which is the lateral collapse of walls and wall framing systems, can lead to collapse of the
138 entire house (van de Lindt and Dao 2009).

139 **Scope**

140 Here, we develop and adapt a component-level performance-based wind engineering assessment
141 framework to evaluate post-disaster housing in resource-limited contexts. We then assess wind performance
142 of twelve core housing designs developed and constructed by NGOs and government agencies after
143 Typhoon Yolanda in the Philippines to examine the probability of 1) roof cladding loss, 2) roof system
144 failure, and 3) wall failure. These failure modes impair occupant safety, drive losses, and result in potential
145 population displacement. To provide recommendations to organizations on how to improve housing
146 resilience, we also use this framework to examine how varying the design of the roof components can
147 improve performance.

148 **Context**

149 We assessed the performance of twelve housing designs (see Fig 1; Table 1) constructed after Supertyphoon
150 Haiyan (locally referred to as Yolanda) in the Philippines, one of the most typhoon-prone countries in the
151 world (Holden and Marshall 2018). Yolanda made landfall in the Philippines on November 8, 2013, killing
152 over 6,000 people (NDRRMC 2014) and damaging or destroying more than 1.1 million homes (Shelter
153 Cluster 2014). At its peak, Yolanda had wind gusts of nearly 380 kph (235 mph) and 1-min sustained winds
154 of 315 kph (196 mph) (Mas et al. 2015). The islands of Leyte and Samar were particularly affected by
155 Yolanda, which first made landfall in Guiuan, Eastern Samar, with a second landfall near Tacloban, Leyte's
156 largest city (Mas et al. 2015). Reconnaissance following Yolanda revealed that most wooden houses were
157 blown away or had severe roof damage, and the most common roof failure mechanism was the CGI tear
158 out around the fastener (Build Change 2014; Chen et al. 2016; Mas et al. 2015).

159 Since Typhoon Yolanda, this region has experienced a number of typhoons, including: Typhoons
160 Ruby (2014), Tisoy (2019), and Ursula (2019). Most recent was Typhoon Ursula (Dec. 2019), which
161 followed a path similar to Yolanda. Maximum gusts experienced during Ursula in Guiuan were 195 kph
162 (120 mph), about half of those experienced during Yolanda. Additional information about the paths of
163 recent typhoons can be found in the Supplemental Information (SI). The authors conducted reconnaissance
164 in Guiuan and Tacloban approximately one month after Typhoon Ursula to assess the performance of

165 houses constructed after Yolanda. This reconnaissance revealed that the most common type of damage
166 experienced during Ursula was loss of CGI panels. Nevertheless, as Fig 2 shows, some wooden houses in
167 Guiuan—including houses constructed by NGOs after Typhoon Yolanda—collapsed due to wall racking.

168 The designs considered in this study (Table 1) consist mainly of one-story houses with a single
169 room. A few designs are two-stories, and two are “loftable”, meaning they were built as one-story houses
170 with space to add an interior second floor. The frames are either RC or wood, with the exception of the
171 “loftable” houses, which have load-bearing masonry or concrete walls. Framed systems use a variety of
172 wall materials: plywood, masonry, concrete, or amakan, which is a woven bamboo material. Roof shapes
173 are both gable and hip, and roof pitch ranges between 20 and 35 degrees. Nearly all of the studied houses
174 with gable roofs resemble Fig 3: CGI panels supported on wooden purlins that were connected to either 3
175 or 4 wooden roof trusses (2 at the gable ends and 1 or 2 in the middle of the structure). Hip roofs have 2 or
176 3 main trusses and 2 or 3 hip trusses on each end. The two “loftable” houses have no trusses, and metal
177 purlins that connect directly to the wall. Additional information and photos of the studied houses can be
178 found in the SI.

179 **Methods**

180 *Overview of Performance Assessment*

181 We assessed the likelihood of failure under wind loading, following the framework reported in Fig 4. This
182 assessment evaluates the performance of the twelve housing typologies in 3-sec wind gusts ranging from
183 90 kph (55 mph, signal 2/tropical storm) to 405 kph (250 mph, signal 5/category 5). Wind pressures are
184 estimated for each velocity on potentially critical roof and wall components using ASCE 7-16 procedures
185 for low-rise buildings (ASCE/SEI 2016). Failure was determined by checking component capacities against
186 demands at a specified wind velocity of interest (step 5 in Fig 4):

$$187 \quad R < (W_U - D), \quad (1)$$

188 where R = capacity of the given component, W_U = uplift wind force on component, and D = force from
189 dead load acting on the component. We identified wall failure by checking whether the capacity of the wall
190 or wall framing system was less than the lateral wind demand, W_L , at a specified wind velocity: $R < W_L$.

192 To account for uncertainty in both the wind loads and the component capacities, we used a Monte Carlo
193 simulation to propagate uncertainty through the assessment.

194 In this study, we draw from van de Lindt and Dao's (2009) limit states to define three performance
195 levels of interest for housing (in order of increasing severity): continued occupancy, life safety, and
196 structural integrity. We relate these performance levels to quantitative measures of the selected component
197 failures (see Table 2). Failure at the *continued occupancy* performance level implies that the structure does
198 not provide protection from the elements; this state is compromised after the first roof cladding panel is
199 lost. This occurs either due to failure at the CGI-fastener interface or failure of the connection between the
200 purlins and the truss.

201 A house does not meet the *life safety* performance level, *i.e.*, it fails to protect occupant safety, if
202 the roof system detaches due to failure of one of the roof-to-wall connections (van de Lindt and Dao 2009).
203 Failure of the roof-to-wall connections not only compromises the primary living space, but potentially
204 undermines the stability of the walls of the house. *Structural integrity* is compromised if the at least one of
205 the walls has insufficient lateral capacity in the absence of the roof diaphragm (van de Lindt and Dao 2009),
206 with specific emphasis herein on the racking of walls in wooden houses. To determine if these performance
207 objectives are achieved, we assess the performance of all four of the components (panel-fastener interface,
208 purlin-to-truss connection, roof-to-wall connection, and walls) that are related to these performance
209 objectives (continued occupancy, life safety, and structural integrity) for each house. By creating a damage
210 fragility for each component, the governing component failure and corresponding performance objectives
211 (Table 2) can be identified. The following section will discuss the component-level failure mechanisms
212 associated with each of these performance levels (third column of Table 2).

213 ***Wind Loading on Houses***

214 Wind pressures were estimated using Equation 2 from ASCE 7 (ASCE/SEI 2016) (step 3 in Fig 4):

$$215 \quad W = q_h [GC_p - GC_{pi}], \quad (2)$$

216

217 where q_h = velocity pressure at the mean roof height, G = gust factor, C_p = external pressure coefficient,
218 and C_{pi} = internal pressure coefficient. The velocity pressure (N/m²) is determined by:

219
$$q_h = 0.613 K_z K_{zt} K_d K_e V^2, \quad (3)$$

220 where K_z = velocity pressure exposure coefficient, K_{zt} = topographic factor, K_d = directionality factor, K_e =
221 ground elevation factor, and V = 3-s gust wind speed (m/s). K_z is based on the height of the structure and
222 the exposure classification; we assumed all houses have an exposure B classification due to their location
223 in built-up terrain consistent with suburban exposure. Because the housing designs we assessed were built
224 in multiple locations and the specific topography around each house was unknown, we did not account for
225 wind speed-up effects and assumed K_{zt} to be 1.0. K_d was taken to be 0.85 to account for the wind direction
226 not likely aligning with the worst-case angle of attack. As all houses were located at sea level, K_e was taken
227 as 1.0 for all designs.

228 *Pressure Coefficients*

229 Unfortunately, the available wind tunnel testing databases (e.g., TPU 2007) did not have pressure
230 coefficients for houses with eaves, so external pressure coefficients, C_p , (step 1a in Fig 4), were determined
231 using Chapters 28 (Main Wind Force Resisting System – Envelope Procedure) and 30 (Components and
232 Cladding) from ASCE 7-16 (ASCE/SEI 2016). These coefficients have been developed based on wind
233 tunnel tests and expert judgment. For panels, fasteners and purlin-to-truss connections, the component and
234 cladding coefficients were used, whereas the roof-to-wall connections and wall frames use the main wind
235 force resisting system coefficients. We again used ASCE 7-16 (ASCE/SEI 2016) pressure coefficients for
236 the regions of the roof where there was an eave because the recent wind tunnel test data (e.g., Parackal et
237 al. 2016) is for designs with more complex geometries than those included in this study.

238 The houses included in this study were not watertight (*i.e.*, there tended to be gaps between the top
239 of the wall and the roof, and windows did not fully close) and the wall material for some houses was
240 permeable (woven bamboo). Therefore, we assumed each house was partially enclosed with an internal
241 pressure coefficient, C_{pi} , of 0.55 (step 1a in Fig 4). While this was likely a conservative estimate for the
242 internal pressure of the intact structure, it is likely representative of the internal pressures the building would

243 experience following envelope breach. For both the internal and external pressures, no redistribution of
244 pressures is considered since our analysis focuses on first or governing component failures.

245 ***Dead Loads***

246 The dead load (step 1b in Fig 4) on the structures is minimal, as these houses are lightweight. Included in
247 the self-weight of the roof are the CGI panels, the wooden purlins, and the wooden roof trusses. Material
248 weights are defined in Table S1 in the SI.

249 ***Component Demands***

250 Based on these loads and the tributary areas of the components, the forces on each component were
251 determined using a load-path analysis based on each component's tributary area. We specifically assumed
252 that all components were simply supported, which is consistent with the design and construction of the
253 houses. Based on our reconnaissance observations, the amakan and plywood walls were also assumed to
254 retain their integrity, forming a diaphragm that transferred the wind pressures acting over the surface to the
255 wall framing. Note that this analysis is intended to identify the first component failure, since load-sharing
256 and pressure redistribution effects after the first failure are not considered when specifying component
257 demands. While failures can propagate following the onset of failure in a given component, this study
258 focused on establishing onset failures, given that a more sophisticated model/analysis could not be
259 developed because of the limited information available about this type of construction and given the
260 reduction in internal pressures caused by the structure changing from partially enclosed to partially open.
261 Moreover, there is insufficient data to calculate new pressures and loads once a roof panel or other
262 component was damaged.

263 ***Wind-Resisting Component and System Capacities***

264 This section explains how we determined the expected capacities for each component and system (step 1c
265 in Fig 4). The SI details specific assumptions for individual housing designs. Failure occurred when the
266 demands in any given component exceeded its capacity according to Eqn. 2. After determining which
267 components had failed for a given demand, we assessed whether a given performance level (Table 2) had
268 been met.

269 *CGI-Fastener Interface Capacities*

270 We considered two failure mechanisms at the CGI-fastener interface: fastener pullout and CGI tear out
271 around the fasteners. The studied houses had two types of fasteners: umbrella nails and roofing screws. The
272 initial pullout capacities of these fasteners were taken from experimental tests of similar metal cladding
273 attached to wooden purlins in Belize (Thurton et al. 2012). However, the withdrawal capacity of nails in
274 wood is dependent on the specific gravity of the wood used, and pullout capacities of 1.3 and 1.4 kN (0.29
275 and 0.31 kips) for umbrella nails and roof screws, respectively, accounted for the greater specific gravity
276 of Filipino coconut lumber (assuming medium hardness; Build Change 2015; Talatala et al. 2014) through
277 the adjustment from ANSI/AWC (2015). The CGI tear-out capacity around the fasteners was calculated as:

278
$$R = c d^\alpha t^\beta f_u^\chi, \quad (4)$$

279 where d = head diameter of the fastener (mm), t = thickness of the CGI panel (mm), and f_u = ultimate
280 strength of the CGI (MPa) (Mahendran and Tang 1999). C , α , β , and χ are constants based on the shape of
281 the metal panels. Once the fastener pullout and panel tear-out capacities were calculated, the lesser value
282 was used as the governing capacity at the panel-fastener interface. We assumed that not all fasteners would
283 be properly placed during construction (not aligned with the centerline of the purlin), and those not properly
284 placed would have a reduction in their capacity. We assumed that 3% of the fasteners would be improperly
285 installed and that both the pullout and tear-out capacities would be reduced according to the triangular
286 distribution from Stewart et al. (2018). Panel failure was then assumed to occur once ten percent or two of
287 its fasteners fail, whichever is greater (Henderson et al. 2013b; Stewart et al. 2018)

288 *Purlin, Truss, and Purlin-to-Truss Connection Capacities*

289 Fig 5 illustrates the two relevant purlin-to-truss connections: hurricane straps and wooden cleats. In six of
290 the housing designs considered, hurricane straps, were used to connect the purlin to the truss. We assumed
291 these connections were similar to the H3 ties provided by Simpson Strong-Tie™, with a capacity of 2.2 kN
292 (0.49 kips) (Simpson Strong-Tie 2019). Four designs used wooden cleats to connect the purlins to the truss;
293 these connections often used only two nails (one nail into purlin and another into the truss). The likely
294 failure mechanism of these connections was nail shear, so we calculated the shear capacity for nails in

295 single shear (ANSI/AWC 2015). Although this shear failure can take on various forms, in almost all cases,
296 the yielding was the governing shear failure mode. The remaining two designs did not have trusses nor
297 purlin-to-truss connections.

298 Although less commonly observed, metal roof panels have been found to be pried from a house
299 with the wooden purlins attached (Ginger et al. 2010; Parackal et al. 2018). To relate purlin-to-truss
300 connection failure to panel failure, we assumed: 1) that all purlin-to-truss connections on a single purlin
301 needed to fail for the purlin to fail, and 2) the purlin at the edge of a roof panel must fail for the panel to
302 fail. These assumptions were based on the observed panel and purlin-to-truss connection failures in the
303 Philippines following Typhoon Ursula, which showed the entire edge purlins failed before roof panel loss
304 occurred. Future studies in other regions may consider different failure criteria (e.g., Parackal et al. 2018)
305 informed by on contextual observations as these will vary with component detailing and regional practice.

306 We were also concerned with failure of the purlin members, but our analysis indicated that other
307 components would fail first and thus such failure would not govern, even in cases with hurricane straps.
308 For this reason, we do not further discuss the capacity of the purlin members. Likewise, trusses were not
309 expected to govern failure given both the size of the wooden truss members and quality of the truss
310 connections as many roof trusses were pre-fabricated off-site.

311 *Roof-to-Wall Connection Capacities*

312 There were six types of roof-to-wall connections in the studied houses: hurricane straps, wooden cleats,
313 bolted wood, steel to concrete, toe-nailed, and wrapped rebar. The hurricane straps used to connect the roof
314 to the wall (Fig 5b, similar to an H2.5 from Simpson Strong-Tie™) were larger and stronger than those
315 used to connect the purlins to the truss; the assumed capacity of these connections was 5.8 kN (1.3 kips)
316 (Ellingwood et al. 2004; Li and Ellingwood 2006). The capacity of the wooden cleats was determined as
317 described above. We also determined the capacity of the bolted wood connections using shear capacity
318 equations from ANSI/AWC (2015). As, the bolted connections used a single bolt to connect the truss to the
319 wall on two sides, we used the shear capacity equations for bolts in double shear. For the designs with
320 bolted connections, neither block shear nor wood splitting controlled. In two designs, steel channel purlins

321 were connected to concrete ring beams at the top of load-bearing wall systems. These connections varied
322 based on contractor and were either partially embedded in concrete or bolted to steel L-angles attached to
323 the walls. We assumed the capacity of the bolted connections was 4.5 kN (1 kip) (Stewart et al. 2018) and
324 that the partially embedded connections had the same capacity. The capacity of the toe-nailed connections
325 was taken from previous literature with similar configuration and member sizes and assumed to be 2.9 kN
326 (0.65 kips) (Cheng 2004; Khan 2012). In the Caputian-Amakan design, “flat bars” were placed at the edge
327 of the roof panels and connected to the foundations in order to tie down the panels. These bars effectively
328 pre-tension the roof system, which we modeled as an additional dead load, thereby, reducing the uplift
329 forces experienced at the roof-to-wall connections. The Bangon and Caputian-Masonry roof-to-wall
330 connections were rebar extending from the tops of the RC columns wrapped around the lower chord of the
331 wooden truss, and, based on the third author’s observations in Haiti, we assumed these connections would
332 not fail (Kijewski-Correa et al. 2017).

333 *Wall-Frame Capacities*

334 Four types of wall-frame systems were included in this study: wood and RC frames and concrete and
335 masonry load-bearing walls. In light-frame wood houses, wall failure from racking can occur under strong
336 wind loads (Liu et al. 1990). In these houses, knee braces as in Fig 3c provide racking resistance (Erikson
337 and Schmidt 2003), with additional lateral resistance provided by the plywood walls (Doudak and Smith
338 2009). For houses with amakan walls, we assumed that only the knee-brace frame provided lateral
339 resistance.

340 To understand the capacity of the knee braces, we referred to tests by Erikson and Schmidt (2003)
341 which revealed that the maximum force carried by the knee brace in an unsheathed wall system was 10.6
342 kN (2.4 kips); however, the knee braces in their systems had notched connections between the brace and
343 beam/column, increasing the capacity compared to the bolted and toe-nailed braces found in the studied
344 houses. Thus, we estimated the strength of the implemented knee-brace system using field data collected
345 after Typhoon Ursula. In Candulo, approximately 50% of the houses experienced racking failures during
346 Ursula (see Fig 2). A wind field map for Ursula is not available, but based on the available wind field data

347 from Typhoon Yolanda (Kunze 2017), which followed a similar path of Ursula, and knowing the relative
348 intensities of the two storms, we estimated that the maximum 3-sec wind gusts in this community during
349 Ursula were 160 kph (100 mph) and that the resultant forces on the walls were 6.5 kN (1.5 kips). We used
350 this value as the median capacity for the knee braces.

351 For plywood houses, we added to the capacity of the knee brace (6.5 kN, 1.5 kips) based on
352 Salenikovich's (2000) tests on walls that are nailed at the base. Salenikovich found that the racking
353 resistance of a 2.4 m (8 ft) and a 3.65 m (12 ft) wall were 3.5 kN/m (240 lb/ft) and 4.5 kN/m (308 lb/ft),
354 respectively. On average, this adjustment increased the capacity of plywood wall frames by a factor of 2.5,
355 which is consistent with other studies(Erikson and Schmidt 2003; Wolfe 1983). For houses with double
356 sheathed walls, we increased the capacity by a factor of 1.9 based on results from Patton-Mallory et al.
357 (1984), Lastly, we reduced the additional capacity provided by the sheathing to account for openings based
358 on tests from Doudak and Smith (2009), who showed that the racking resistance of plywood walls with
359 door and window openings were reduced by 55% and 50%, respectively.

360 Previous reconnaissance has documented wall failures due to uplift tensioning unreinforced
361 masonry walls in hurricanes due to the absence of ring beams (Kijewski-Correa et al. 2017) or vertical
362 reinforcement in walls (Suaris and Khan 1995). The houses included in this study contained both of these
363 elements, so wall assessments were not included for RC (either frame or load bearing) and masonry
364 structures as it was expected that the lateral capacity of these walls remains sufficient to resist wind loads
365 even once the roof system dislodges.

366 ***Treatment of uncertainty***

367 We used a Monte Carlo simulation to propagate the uncertainty in the wind loads and component capacities
368 through the performance assessment (step 7 in Fig 4). The distribution parameters for the random variables
369 are summarized in Table 3. Component capacities are assumed to be uncorrelated, *i.e.*, realizations of
370 capacities for each component are independent of the capacities of other components (whether the same
371 component type or not).

372

373 ***Sensitivity analysis***

374 We also conducted a sensitivity analysis to assess the effect of design changes on a housing type's wind
375 performance. Table 4 summarizes the variations we considered, which are each feasible to implement by
376 organizations constructing post-disaster housing.

377 **Results**

378 Using the framework described above, we assessed the performance of twelve housing designs. In this
379 section, we present the assessment of one housing design in detail, discussing first the expected failure
380 sequence and its relation to the selected performance objectives, and then each failure mechanism in detail.
381 We then compare the expected performance of the remaining houses. While the fragilities are presented by
382 component, each component failure is related to a performance level (Table 2) as an indicator of housing
383 system performance. We also discuss the findings of the impact of design modifications on the performance
384 assessments. All wind speeds herein are defined as 3-second gusts.

385 ***Wind Performance of Candulo House Design***

386 Fig 6 shows the estimated distributions of the wind speed instigating the first failure of each component in
387 the Candulo house (Fig 1d) and their relationship to the performance levels detailed in Table 2. The first
388 components expected to fail in this design are the walls, indicating the structural integrity performance
389 objective is realized, at an estimated median wind speed of 160 kph (100 mph), *i.e.*, a signal 3
390 typhoon/category 2 hurricane. These wall frames are unbraced and have little sheathing stiffness (amakan
391 walls), resulting in limited lateral resistance. The houses damaged by Typhoon Ursula in Fig 2 were located
392 in Candulo, and community leaders estimated that 50% of these houses were damaged or destroyed during
393 this storm, indicating that our results are consistent with the observed damage. To the best of our knowledge,
394 there were no reported wall failures during Tropical Storm Urduja, and our analysis predicts a low
395 likelihood of wall failure in wind speeds similar to those experienced in that storm.

396 The analysis also indicates that roof failure occurs at higher wind speeds than wall failure: a median
397 wind speed of 220 kph (137 mph). Of the roof system components, the analysis predicts that failure initiates
398 at the CGI-fastener interface. It is expected that the CGI panels will detach due to tear out around the heads

399 of the umbrella nails used to fasten the panels to the purlins. The analysis also indicates that all analyzed
400 components (walls, fasteners, purlin-to-truss and roof-to-wall connections) are predicted to fail in a future
401 typhoon as strong as Yolanda. However, we note that the wind pressures do not account for redistribution
402 after failure; as we witnessed in Candulo following Typhoon Ursula (see Fig 2), the roofs often remained
403 intact after the racking failure. The other failure modes of roof-to-wall and purlin-to-truss connections are
404 expected to have residual capacity beyond the load required to cause failure of the roof panels or walls. We
405 therefore do not expect these failures to govern this design.

406 ***Wind Performance of Other Houses***

407 Table 5 summarizes the expected failure mechanisms of the other housing designs, based on the median
408 wind speed causing the onset of failure in four components: the first roof panel (1) considering capacity of
409 the CGI-fastener interface and (2) considering purlin-to-truss connection, (3) roof-to-wall connections, and
410 (4) wall-frame systems.

411 Fig 7 summarizes the onset failure wind speeds for the four components investigated in each house
412 and their corresponding performance levels, and Fig 8 presents the results of the sensitivity analysis. The
413 sensitivity analysis considers a gable roof and hip roof design with near-identical height, length, width, and
414 number of purlins, based on the Bangon and Caputian-Amakan designs. The following sections discuss the
415 observed governing failure mechanisms and the sensitivity analysis results for the purlin-to-truss
416 connections, CGI-fastener interface, and roof-to-wall connections.

417 ***Governing Failure Mechanisms***

418 We found three failure mechanisms governed the houses assessed in this study, linked to two performance
419 levels: structural integrity and continued occupancy. Wall-frame system racking (structural integrity
420 performance level) was the governing failure (3 of 12 designs), particularly for houses with amakan walls.
421 The most common (9 of 12 designs) were governed by roof panel failure (continued occupancy performance
422 level), with an almost even distribution of panel failures limited by the capacity of the CGI-fastener
423 interface and purlin-to-truss connection. For gable roofs, panel failure is likely to initiate with failure of the
424 purlin-to-truss connection; whereas, for hip roofs, panel failure is likely to occur because of failure at the

425 CGI-fastener interface. This difference in panel failure mechanism for hip and gable roofs is due to a
426 combination of the increased capacity of the greater number of purlin-to-truss connections as well as
427 reduced demand on the hip roofs (more favorable aerodynamic shape), which decrease the potential for
428 purlin-to-truss connection failure.

429 This analysis is consistent with the communities' previous typhoon experience. The most common
430 damage reported by households in these communities following Typhoon Ursula was roof cover loss, with
431 approximately 40% of households stating that their roof panels had been damaged or blew off. Prevalence
432 of roof damage was highest in the communities of Linao, San Pablo, and Sohoton. In these communities,
433 the median wind speed at which roof panel failure occurs (Table 4) is less than the maximum wind speeds
434 experienced during Typhoon Ursula. Very few respondents in Caputian (masonry houses) or Sagasumbut
435 reported roof panel loss, and our analysis indicates that the median wind speed for panel failure in these
436 houses is greater than the wind speeds of Ursula. These analysis results are also consistent with reports
437 following Typhoon Yolanda that found, when houses were not completely destroyed, roof cover loss was
438 the most common damage observed (Mas et al. 2015)

439 *Wall-Frame Systems Failure (Structural Integrity Performance Level)*

440 Fig 7a reports the median wind speeds (kph) of onset wall failures for houses with wooden wall-frame
441 systems . For houses with amakan walls, wall failure was always the governing failure except for the
442 Sohoton-Amakan design. Both the Candulo and Caputian-Amakan designs have strong roofs with hurricane
443 straps and roof ties, respectively, and are expected to experience wall racking in our analysis. Indeed, we
444 documented this failure in both communities following Typhoon Ursula, with greater prevalence in
445 Candulo (see Fig 2) versus Caputian, which agrees with our analysis results. The predicted median wind
446 speed of racking failure in Caputian was 190 kph (118), which is greater than the estimated wind gusts
447 experienced during Ursula (164 kph (102 mph)). Therefore, the analysis is consistent with the observation
448 that some, but well less than 50%, of the Caputian-Amakan houses failed due to racking in Ursula. Note
449 that the footprint of the Sohoton-Amakan design is smaller than the other houses, reducing the wall loads,

450 and thus panel failure at the purlin-to-truss connections governs in the analysis; we did not observe any
451 racking failures of this design after Typhoon Ursula.

452 The analysis does not expect houses with plywood walls to be as vulnerable to wall racking. The
453 only exception is the Sagasumbut-2Story design, which experiences racking at a median wind speed 13 kph
454 (8 mph) less than that instigating the loss of the first roof panel due to fastener failure. Because the house
455 is two stories tall and has only two walls in each orientation, the walls on the first floor must carry a larger
456 load than either the 1-story designs or the Sagasumbut-Duplex design, which has interior partition walls.

457 Wall-frame racking that impairs structural integrity in these houses is expected at low wind speeds
458 due to the limited capacity of the knee braces and flexibility of the amakan walls. As we witnessed after
459 Typhoon Ursula, houses that experience this failure mechanism either collapsed or were uninhabitable due
460 to residual drift. Amakan, or walls of a similar lightweight, woven material, are viewed by some post-
461 disaster housing practitioners as a preferable alternative both because they are a permeable material that
462 increases comfort in hot environments and because they expect any damage to be easily repairable.
463 Practitioners expect that the amakan walls will “blow-out,” reducing the drag coefficient and allowing the
464 structural frame to remain intact, possibly with some minor racking that is easily correctable once the storm
465 has passed. However, reconnaissance after Typhoon Ursula revealed that these walls do not “blow-out”,
466 but instead transfer sufficient load into the frames, resulting in story-mechanisms that are not easily
467 repairable. We therefore recommend that organizations consider other wall materials with greater stiffness
468 and/or provide appropriate lateral bracing and connections that can ensure load path continuity. This
469 recommendation is particularly important where roof systems have been strengthened as in Candulo
470 (hurricane straps) and Caputian (roof ties with “flat bars”).

471 *Purlin-to-Truss Connection Failures (Continued Occupancy Performance Level)*

472 Two different types of purlin-to-truss connections were used in the studied houses, wooden cleats and
473 hurricane straps, with differing performance shown in Fig 7b. While the uplift capacity of the hurricane
474 straps is more than double that of the wooden cleats, the most influential factor in the performance of the
475 purlin-to-truss connections is the roof shape. Both the cleat and strap connections on the hip roofs perform

476 better than both connection types on gable roofs, a result of the hip roof's reduced wind pressures (up to
477 80% at the roof ridge and 25% on the roof edge).

478 Because the performance of the purlin-to-truss connection depends on both the connection type and
479 roof shape, we conducted a sensitivity analysis to explore the effects of these two design features on panel
480 failure rates, as shown in Fig 8a. For both hip and gable roofs, replacing wooden cleats with hurricane straps
481 improves performance, increasing the median wind resistance by approximately 45%. Changing the roof
482 shape from gable to hip and maintaining the purlin-to-truss connection also improves performance by 42%
483 for both cleats and straps. So, while a gable roof with hurricane straps is expected to experience its first
484 panel failure at nearly the same median wind speed as a hip roof with wooden cleats, a hip roof with straps
485 will outperform both designs by almost a factor of two. However, the use of hip roofs, particularly with
486 hurricane straps, is only advisable if the walls have adequate capacity to transfer the forces from this
487 substantially stronger roof system to the foundation.

488 *Failures at the CGI-Fastener Interface (Continued Occupancy Performance Level)*

489 Fig 7c provides results for failure of the CGI panel loss due to failure at the CGI-fastener interface. The
490 first panel failure occurs over a large range of wind speeds, depending on the housing design, from
491 approximately 185 kph (115 mph) to 305 kph (190 mph). This suggests that failure at the CGI-fastener
492 interface is unlikely in weaker storms, like Tropical Storm Urduja, but is expected in many of the housing
493 types in storms like Typhoon Ursula. As shown in Fig 7c there is no trend between roof shape or roof
494 elevation and these panel failure rates.

495 Fig 8c and d examine how different CGI gauges and fastener spacings affected fastener and panel
496 failures. Increasing panel thickness from 28 to 26 gauge and 26 to 24 gauge increased the median wind
497 speeds causing failure by 22% and 34%, respectively, for both hip and gable roofs. While panels on the hip
498 roof performed slightly better than those on gable roofs (by 9%), panel thickness was more important
499 because the panel performance was governed by CGI tear out around the fasteners. Decreasing the fastener
500 spacing on the interior purlin lines from 300mm (12in) to 150mm (6in) (exterior purlin lines were assumed

501 to already have a spacing of 150mm (6in)) improved the median wind speed causing failure by an average
502 of 41%. Similar to panel thickness, the trend is not dependent on the roof shape.

503 We also assessed whether increasing the CGI thickness or fastener spacing is more beneficial to
504 panel performance. Fig 8e shows that both have a considerable effect on panel performance: decreasing the
505 interior nail spacing from 300mm (12in) to 150mm (6in) improves panel performance, in terms of median
506 wind speed, by an average of 49% regardless of panel thickness, while increasing panel thickness and
507 maintaining fastener spacing improves performance by 28%. Thus, we recommend that organizations
508 providing post-disaster housing, whenever possible, use at least 26-gauge CGI (24-gauge is preferable) and
509 at most 150mm (6in) spacings for both edge and interior fastener lines. The CGI panel thickness is
510 especially important because this failure mode increases in prevalence as CGI corrodes with age, which is
511 not considered here. While there are budgetary implications, notably for increasing panel thickness, greater
512 fastener density has minor impacts to material costs and should be advocated at minimum. The associated
513 increase in installation efforts could be offset through community volunteer labor.

514 *Roof-to-Wall Connection Failure (Life Safety Performance Level)*

515 Roof-to-wall connection failure was not anticipated to govern any of the considered designs, which agrees
516 with our reconnaissance after Typhoon Ursula. The median wind speeds associated with failure of the roof-
517 to-wall connections are shown in Fig 7d. The good performance of these connections is based primarily on
518 the connection type rather than the house geometry. Bolted connections unsurprisingly, perform the best.
519 Next, hurricane straps, and toe-nailed connections plus hurricane straps, perform similarly, with capacity
520 11-24% less than bolted connections. Toe-nailed and wooden cleat connections are expected to perform
521 the worst. The expected performance of the wooden cleat connection appears to be better than that of a toe-
522 nailed connection because, in this case, the house that included wooden cleats at the roof-to-wall connection
523 also used “flat bars” to tie the roof to the foundations.

524 This suggests that bolted connections may be the best roof-to-wall connections option (Fig 8b),
525 though this is very much dependent on the dimensional and material properties of the timber used and the
526 geometry of the connection. In connections with multiple bolts, which was not the case in any of this study’s

527 housing designs, wood fracturing or block shear can govern; thus, the connections must be appropriately
528 designed to avoid these failure mechanisms. In light of the above, hurricane straps remain the most
529 consistent means of assuring effective roof-to-wall load transfers. However, as the roof-to-wall connection
530 is not the governing failure mode in any of the designs, and noted vulnerabilities remain in other elements
531 of the load path that could even be exacerbated by improved roof-to-wall connections, organizational
532 resources are likely better spent at first improving wall strength or roof panel performance.

533 *Additional Considerations*

534 We investigated two additional design decisions: purlin spacing and eave length. Both of these decisions
535 affect the performance of multiple components, so we discuss them here.

536 Purlin spacing affects the performance of both the CGI-fastener interface and the purlin-to-truss
537 connections. As shown in Fig 8f, decreasing the purlin spacing from 600mm (24 in) to 450mm (18 in) and
538 from 450mm (18 in) to 300mm (12 in) on a hip roof increases the median wind speed instigating panel loss
539 due to failure at the CGI-fastener interface by 30% and 12%, respectively. On a gable roof, these reductions
540 in purlin spacing result in a 7% increase in the median wind speed at which panel loss due to purlin-to-truss
541 connection failure occurs. Decreasing purlin spacing also improves the performance at the purlin-to-truss
542 connections on a hip roof and the CGI-fastener interface on a gable roof, though these were not identified
543 as governing failure mechanisms in the initial assessment. While decreasing purlin spacing is an option to
544 improve roof performance in areas where access to thicker CGI is limited, it could be challenging to
545 implement in regions with limited access to wood.

546 The additional uplift forces caused by extending the eaves results in poorer performance of the roof
547 panels. Adding a 0.5m (1.6 ft) and 1.0m (3.3 ft) eave can decrease the median wind speed at which panel
548 failure occurs by 10% and 25%, respectively. These forces also increase the loads on the roof-to-wall
549 connections, but these connections were not the governing failure mechanism in the initial analysis, even
550 for the longer eave case. Many households increase the eave length to provide protection from the sun and
551 rain, so roofs should be designed to account for this increase in wind uplift demand.

552 *System Effects*

553 While we have provided recommendations for improving the performance of the roof panels and roof-to-
554 wall connections, load path is jeopardized if organizations do not consider the wall and roof together. They
555 must use care in understanding the capacity of wall systems when strengthening roofs (Kijewski-Correa et
556 al. 2017). From a performance-based engineering perspective, it is preferable to have a weaker roof that
557 will experience roof cover loss because this primarily impairs continued occupancy, than to have a strong
558 roof that experiences no damage but instead results in higher demands on more vulnerable walls and impairs
559 structural integrity. Roof cover loss is comparatively easier to repair, and, while flying CGI panels can
560 cause injury and damage to neighboring structures, the safety of occupants sheltering in place and the speed
561 of the recovery process are both improved through the prevention of severe damage or collapse at the system
562 level as a result of wall failure. Therefore, organizations should only strengthen the roof, either at the CGI-
563 fastener interface, purlin-to-truss connection, or roof-to-wall connection, if an accompanying analysis
564 suggests the walls have sufficient capacity to resist the resulting increased load demands.

565 Although we did not expect the houses with RC frames or masonry walls to be damaged, some
566 NGOs continue to implement load bearing unreinforced masonry walls without any confining elements or
567 reinforcement. Reconnaissance following Hurricane Matthew in Haiti found substantial damage to
568 unreinforced masonry walls due to uplift at the roof-to-wall connections, at times leading to complete wall
569 failure and thus system-level collapse (Kijewski-Correa et al. 2017). Organizations that choose to build
570 with masonry must ensure that appropriate confining elements and ideally wall reinforcement are included
571 so that the wall system has adequate strength to complete the load transfer from the roof to the foundation.

572 Lastly, some households had added extensions to their house – a modification that could either
573 increase or decrease a house's wind vulnerability depending on the addition's geometry and lateral
574 resistance. Nevertheless, we calculated that in Candulo, the community that experienced the most wall
575 racking during Typhoon Ursula, extensions would need to increase the current wall capacity by 180% in
576 order for wall racking to not be the governing failure mode.

577 **Limitations and Future Work**

578 While this study advances the knowledge of the performance of non-engineered post-disaster housing in
579 typhoons, there is uncertainty about the materials and design of these structures. These analyses are further
580 limited by unavailability of data on the capacities of components and connections commonly found in
581 houses constructed in resource-limited communities. Additional experimental tests of context-specific
582 connections and assemblies would improve the accuracy of the models and findings. We particularly
583 recommend testing of wooden cleat connections and wooden frames with plywood and amakan walls. As
584 organic materials are often more accessible than commercial products like hurricane straps, it is important
585 to explore strategies to improve the capacity of such locally available connection details and wall
586 assemblies. In addition, our assumptions about variability in capacities (Table 3) are likely optimistic for a
587 resource-limited context and future work many consider a larger coefficient of variation, or a higher rate of
588 improperly installed fasteners; however, we do not expect these changes to greatly influence overall trends.
589 Additionally, fatigue due to cyclic loading in typhoons has been documented (Boughton and Reardon 1984)
590 and will affect the performance of the components included in this study, particularly hurricane straps and
591 capacity of CGI cladding at the panel-fastener interface. However, given the limited data on the specific
592 materials and connections used in the studied houses, we did not consider the effects of low-cycle fatigue
593 in this study. We suggest that these effects be considered in future work.

594 This study is further limited by the availability of wind pressure distributions for structures with
595 the geometries and eave lengths found in the houses included in this study. Wind-tunnel tests of homes with
596 traditional geometries, particularly related to roof slope and eaves, two critical parameters for aerodynamic
597 loading as well as ventilation and shading in tropical climates, would reduce the uncertainty in load
598 demands. Moreover, wind pressures were not redistributed after failure of the first component, which
599 changed both the surface area as well as the aerodynamic properties, limiting the interpretation of the failure
600 sequence expected in these houses. Future investigations should consider more detailed finite element
601 modeling of critical elements of the load path to capture load sharing along with the redistribution of
602 pressures and load paths after the envelope has been breached. Lastly, we assessed the performance of

603 newly constructed houses and did not account for deterioration of materials or use of lower-quality
604 materials. In particular, our analysis did not account for corrosion of CGI or wood deterioration, both of
605 which have been observed and may influence performance. Future work should examine the performance
606 over the entire lifecycle to provide organizations with a more complete understanding of the investments
607 that will lead to long-term resilience.

608 **Conclusions**

609 In this study, we provided a framework for component-level performance-based wind engineering
610 assessment of post-disaster housing in resource-limited contexts and evaluated the wind performance of
611 twelve housing types built by organizations in the Philippines after Typhoon Yolanda. While NGOs and
612 government agencies build such houses after disasters with the goal of increasing post-disaster housing
613 safety, their performance has not been assessed by an engineering analysis, limiting the ability to make
614 recommendations to further improve safety. To address this need, we use component-level performance-
615 based methods to quantify the median wind speeds causing the onset of common failure mechanisms related
616 to three performance objectives and explore how minor changes in these designs might improve
617 performance.

618 We found that the wall-framing system (and the relative capacity of the roof and wall systems) was
619 the design feature that dictated the governing failure mode. Specifically, wood-frame houses with woven
620 amakan walls, with one exception, were governed by wall racking (3 of 12 cases), failing to meet the
621 structural integrity performance level and, thus, endangering occupants. These results agreed with
622 reconnaissance following Typhoon Ursula. Walls were expected to fail at an average 3-sec gust of 180 kph
623 (112 mph), which is equivalent to a low-strength category 3/signal 4 storm and is less than the maximum
624 3-sec wind gusts recently experienced at the studied locations during Typhoon Ursula. Houses with
625 plywood walls are not expected to fail until an average wind speed of 230 kph (143 mph) due to the added
626 capacity from the plywood sheathing. The remaining nine designs were governed by roof cover loss, failing
627 at the continued occupancy performance level, either due to failure at the CGI-fastener interface or purlin-
628 to-truss connection.

629 For houses with gable roofs, the first panel loss is expected to occur at an average 3-sec gust of 160
630 kph (100 mph), equivalent to a category 2/signal 3 storm, and for hip roofs at an average of 215 kph (135
631 mph), equivalent to a category 4/signal 4 storm. Panel loss on hip roofs was the result of fastener failure,
632 while purlin-to-truss connection failure governed gable roofs. For failure at the CGI-fastener interface,
633 decreasing nail spacing from 300mm (12in) to 150mm (6in) along all purlin lines, is the most beneficial
634 modification, increasing the wind speed at which the failure occurs by 40%, or again, an entire signal rating.
635 Additionally, increasing panel thickness improves performance by 21 to 35%. Replacing wooden cleats
636 with hurricane straps at the purlin-to-truss connections can increase capacity by 45%, or an entire signal
637 rating (*e.g.*, from a signal 2 to a signal 3 storm).

638 Roof-to-wall connections, related to the life safety performance level, were not expected to govern
639 the failure of any of the studied houses.

640 From this analysis, we are able to compare across the housing designs, showing that houses with
641 hip roofs, hurricane straps, shorter eaves, more-closely spaced fasteners and purlins, and plywood-sheathed
642 walls perform better, and quantifying the relative improvement (in terms of wind speed) associated with
643 these changes. Therefore, we recommend that practitioners consider a variety of design changes, including
644 using hip roofs, thicker gauge CGI, decreased fastener spacing, and hurricane straps. The most influential
645 improvements for vulnerable roofs were decreasing nail spacing and using hurricane straps. Most
646 importantly, though, we recommend improving the resistance of the walls in wood frame housing to
647 consider the entire load path when selecting the components to strengthen. We found that houses with weak
648 walls and strong roofs were likely to experience racking and even collapse, affirming reconnaissance
649 observations that this is the largest threat to occupant safety. It is preferable to have a weaker roof that will
650 experience panel loss and relieve pressure on the walls than to have a roof that remains intact and propagates
651 higher demands to the walls. In particular, we recommend using a stronger and stiffer wall material, such
652 as plywood, instead of a porous, woven material like amakan. If materials like amakan are used for the
653 walls, it is crucial that lateral strength of the system be enhanced through additional bracing.

654 This research expanded the study of housing wind performance from typical structures built in
655 North America and Australia to include post-disaster housing in resource-limited communities. This study
656 focused on performance of post-disaster housing built after a typhoon in the Philippines; thus, material and
657 geometry assumptions were based on a specific context, though many features have commonalities
658 worldwide. However, future work can build upon this framework, adjusting the assumptions and designs
659 for different post-disaster events, and indeed housing built by households pre-disaster, in other resource-
660 limited communities. The need for understanding post-disaster housing performance in order to identify
661 those features that most improve housing performance on a limited budget is likely to grow in future years
662 with an increase in disaster frequency and severity (UNISDR 2015). Thus, we anticipate that this framework
663 can be adjusted accordingly for use in assessing standardized housing designs in new contexts.

664 **Data Availability Statement**

665 Some or all data, models, or code that support the findings of this study are available from the corresponding
666 author upon reasonable request, including measurements of studied house designs and wind analysis code.

667 **Acknowledgments**

668 We thank the households that participated in this research, allowing us access to their homes. We
669 acknowledge our research assistants, Dina Pelayo, Denver Evangelista, Eugenio Boco, Hyacinth Raga,
670 Angelou Cinco, Darlyn Diang, and Kristhyl Tunggolh for their assistance in collecting housing
671 measurements, photos, and materials, and Dr. Matthew Koschmann and Briar Goldwyn for their assistance
672 with reconnaissance following Typhoon Ursula. Additionally, we thank the organizations, Dr. Aaron
673 Opdyke, and Dr. Shaye Palagi for information about the housing designs.

674 This material is based upon work supported by the National Science Foundation (NSF) Award
675 #1901808, a USAID/OFDA Graduate Fellowship in Humanitarian Shelter and Settlements, Univ. of
676 Colorado Innovation Seed Grant, and the U.S. Dept. of Education's GAANN #P200A150042. Any
677 opinions, findings, and conclusions or recommendations expressed in this material are those of the authors
678 and do not necessarily reflect the views of NSF, USAID/OFDA, the RIO, or the U.S. Dept. of Education.

679 **Supplemental Materials**

680 Table S1 and Figs. S1-S25 are available online in the ASCE Library (ascelibrary.org).

681 **References**

682 ANSI/AWC. (2015). *National Design Specification for Wood Construction 2015 Edition*. American Wood
683 Council, Leesburg, VA.

684 ASCE/SEI. (2016). *Minimum Design Loads and Associated Criteria for Buildings and Other Structures*.
685 ASCE/SEI 7-16, Reston, VA.

686 Barbato, M., Petrini, F., Unnikrishnan, V. U., and Ciampoli, M. (2013). "Performance-Based Hurricane
687 Engineering (PBHE) framework." *Structural Safety*, 45, 24–35.

688 Boughton, G. N., and Reardon, G. F. (1984). *Simulated Wind Load Tests on the Tongan Hurricane House*.
689 Technical Report, Technical Report, Cyclone Testing Station, James Cook University, Townsville,
690 Australia.

691 Build Change. (2014). *Post-Disaster Reconnaissance Report: Damage Assessment and Housing and
692 Markets Survey 2013 Bohol Earthquake and Typhoon Yolanda*. Build Change, Philippines.

693 Build Change. (2015). "Testing of Coconut Lumber." Build Change Philippines.

694 Chen, S. E., Leeman, M. E., English, B. J., Kennedy, A. B., Masters, F. J., Pinelli, J.-P., Pang, W., Rullan-
695 Rodriguez, J. A., Satyanarayana, P., Calvo, J., Murugan, B., and Natarajan, C. (2016). "Basic
696 Structure System Rating of Post-Super Typhoon Haiyan Structures in Tacloban and East Guiuan,
697 Philippines." *Journal of Performance of Constructed Facilities*, 30(5).

698 Cheng, J. (2004). "Testing and analysis of the toe-nailed connection in the residential roof-to-wall system."
699 *Forest Products Journal*, 54(4), 58–65.

700 Clinton, W. (2006). *Lessons Learned from Tsunami Recovery: Key Propositions for Building Back Better*.
701 United Nations, New York.

702 CRED, and UNISDR. (2018). *Economic Losses, Poverty, and Disasters 1998-2017*. UNISDR, Geneva.

703 Da Silva, J., and Batchelor, V. (2010). "Indonesia: Understanding Agency Policy in a National Context."
704 *Building Back Better: Delivering People-centred Housing Reconstruction at Scale*, T. Schilderman
705 and M. Lyons, eds., Practical Action Publishing Ltd, Rugby, UK, 135–161.

706 Doudak, G., and Smith, I. (2009). "Capacities of OSB-Sheathed Light-Frame Shear-Wall Panels with or
707 without Perforations." *Journal of Structural Engineering*, 135(3), 326–329.

708 Ellingwood, B. (2015). "Performance-based engineering for multiple hazards: The role of structural
709 reliability and risk assessment." *Proceedings of the 2nd International Conference on Performance-
710 based and Life-cycle Structural Engineering*, Brisbane, Australia, 2–7.

711 Ellingwood, B. R., Rosowsky, D. V., Li, Y., and Kim, J. H. (2004). "Fragility Assessment of Light-Frame
712 Wood Construction Subjected to Wind and Earthquake Hazards." *Journal of Structural
713 Engineering*, 130(12), 1921–1930.

714 Erikson, R. G., and Schmidt, R. J. (2003). *Behavior of Traditional Timber Frame Structures Subjected to
715 Lateral Load*. Department of Civil and Architectural Engineering, University of Wyoming,
716 Laramie, WY, 1–229.

717 Gavanski, E., and Kopp, G. A. (2017). "Fragility Assessment of Roof-to-Wall Connection Failures for
718 Wood-Frame Houses in High Winds." *ASCE-ASME Journal of Risk and Uncertainty in
719 Engineering Systems, Part A: Civil Engineering*, 3(4).

720 Ginger, J. D., Henderson, D. J., Edwards, M., and Holmes, J. (2010). "Housing damage in windstorms and
721 mitigation for Australia." *Proceedings of 2010 APEC-WW and IG-WRDRR Joint Workshop: Wind-
722 Related Disaster Risk Reduction Activities in Asia-Pacific Region and Cooperative Actions*,
723 Incheon, Korea, 1–18.

724 Goyal, P. K., Datta, T. K., and Vijay, V. K. (2012). "Vulnerability of rural houses to cyclonic wind."
725 *International Journal of Disaster Resilience in the Built Environment*, 3(1), 20–41.

726 Harriss, L., Parrack, C., and Jordan, Z. (2020). "Building safety in humanitarian programmes that support
727 post-disaster shelter self-recovery: an evidence review." *Disasters*, 44(2), 307–335.

728 Henderson, D. J., and Ginger, J. D. (2007). "Vulnerability model of an Australian high-set house subjected
729 to cyclonic wind loading." *Wind and Structures*, 10(3), 269–285.

730 Henderson, D. J., Morrison, M. J., and Kopp, G. A. (2013a). "Response of toe-nailed, roof-to-wall
731 connections to extreme wind loads in a full-scale, timber-framed, hip roof." *Engineering
732 Structures*, 56, 1474–1483.

733 Henderson, D., Williams, C., Gavanski, E., and Kopp, G. A. (2013b). "Failure mechanisms of roof
734 sheathing under fluctuating wind loads." *Journal of Wind Engineering and Industrial
735 Aerodynamics*, 114, 27–37.

736 Holden, W. N., and Marshall, S. J. (2018). "Climate Change and Typhoons in the Philippines: Extreme
737 Weather Events in the Anthropocene." *Integrating Disaster Science and Management*, Elsevier,
738 407–421.

739 Khan, M. (2012). "Load-sharing of toe-nailed, roof-to-wall connections under extreme wind loads in wood-
740 frame houses." M.S. Thesis, University of Western Ontario, Ontario, Canada.

741 Kijewski-Correa, T., Kennedy, A., Prevatt, D., and Taflanidis, A. (2017). "Field Reconnaissance Following
742 the Passage of Hurricane Matthew over Haiti's Tiburon Peninsula." *13th Americas Conference on
743 Wind Engineering*, Gainesville, Florida.

744 Kijewski-Correa, T., Taflanidis, A. A., Mix, D., and Kavanagh, R. (2012). "Empowerment Model for
745 Sustainable Residential Reconstruction in Léogâne, Haiti, after the January 2010 Earthquake." *Leadership and Management in Engineering*, 12(4), 271–287.

747 Kunze, S. (2017). *Unraveling the Effects of Tropical Cyclones on Economic Sectors Worldwide*. Working
748 Paper, University of Heidelberg, Department of Economics, Heidelberg, Germany.

749 Lee, K. H., and Rosowsky, D. V. (2005). "Fragility assessment for roof sheathing failure in high wind
750 regions." *Engineering Structures*, 27(6), 857–868.

751 Li, Y., and Ellingwood, B. R. (2006). "Hurricane damage to residential construction in the US: Importance
752 of uncertainty modeling in risk assessment." *Engineering Structures*, 28(7), 1009–1018.

753 van de Lindt, J. W., and Dao, T. N. (2009). "Performance-based wind engineering for wood-frame
754 buildings." *Journal of Structural Engineering*, 135(2), 169–177.

755 Liu, H., Gopalaratnam, V. S., and Nateghi, F. (1990). "Improving wind resistance of wood-frame houses." *Journal of Wind Engineering and Industrial Aerodynamics*, 36, 699–707.

757 Liu-Marques, R., Conklin, W., and Chowdhury, A. (2012). *Shelter and Component Testing OFDA
758 Transitional Shelters: Materials, Techniques, and Structures*. International Hurricane Research
759 Center, Florida International University, Miami, FL.

760 Lyons, M. (2009). "Building Back Better: The Large-Scale Impact of Small-Scale Approaches to
761 Reconstruction." *World Development*, 37(2), 385–398.

762 Mahendran, M., and Tang, R. B. (1999). "Pull-through strength of high tensile steel cladding systems." *Australian Structural Engineering Transactions*, 2, 37–50.

764 Mas, E., Bricker, J., Kure, S., Adriano, B., Yi, C., Suppasri, A., and Koshimura, S. (2015). "Field survey
765 report and satellite image interpretation of the 2013 Super Typhoon Haiyan in the Philippines." *Natural Hazards and Earth System Science*, 15(4), 805–816.

767 Morrison, M. J., Henderson, D. J., and Kopp, G. A. (2012). "The response of a wood-frame, gable roof to
768 fluctuating wind loads." *Engineering Structures*, 41, 498–509.

769 Morrison, M. J., and Kopp, G. A. (2011). "Performance of toe-nail connections under realistic wind
770 loading." *Engineering Structures*, 33(1), 69–76.

771 Mukhopadhyay, P., and Dutta, S. C. (2012). "Strongest Cyclone of the New Millennium in the Bay of
772 Bengal: Strategy of RVS for Nonengineered Structures." *Natural Hazards Review*, 13(2), 97–105.

773 NDRRMC. (2014). *Final Report Re Effects of Typhoon "Yolanda" (Haiyan)*. National Disaster Risk
774 Reduction and Management Council, Quezon City.

775 Opdyke, A., Javernick-Will, A., and Koschmann, M. (2019). "Assessing the Impact of Household
776 Participation on Satisfaction and Safe Design in Humanitarian Shelter Projects." *Disasters*, 43(4),
777 926–953.

778 Parackal, K. I., Ginger, J. D., and Henderson, D. J. (2018). "Wind load fluctuations on roof batten to
779 rafter/truss connections." *Journal of Wind Engineering and Industrial Aerodynamics*, 175, 193–
780 201.

781 Parackal, K. I., Humphreys, M. T., Ginger, J. D., and Henderson, D. J. (2016). "Wind loads on
782 contemporary Australian housing." *Australian Journal of Structural Engineering*, 17(2), 136–150.

783 Patton-Mallory, M., Gutkowski, R. M., and Soltis, L. A. (1984). *Racking Performance of Light-frame Walls
784 Sheathed on Two Sides*. U.S. Department of Agriculture, Forest Service, Forest Products
785 Laboratory.

786 Peacock, W. G., Dash, N., and Zhang, Y. (2007). "Sheltering and housing recovery following disaster."
787 *Handbook of disaster research*, H. Rodriguez, E. L. Quarantelli, and R. R. Dynes, eds., Springer,
788 New York, 258–274.

789 Philippines Shelter Cluster. (2014). "8 Build Back Safer Key Messages." Shelter Cluster.

790 Prevatt, D. O., Dupigny-Giroux, L.-A., and Masters, F. J. (2010). "Engineering Perspectives on Reducing
791 Hurricane Damage to Housing in CARICOM Caribbean Islands." *Natural Hazards Review*, 11(4),
792 140–150.

793 Rentschler, J. E. (2013). *Why Resilience Matters: The Poverty Impacts of Disasters*. Policy Research
794 Working Paper, World Bank.

795 Salenikovich, A. (2000). "The Racking Performance of Light-Frame Shear Walls." Ph.D. Thesis, Virginia
796 Tech, Blacksburg, VA.

797 Schilderman, T. (2010). "Putting People at the Centre of Reconstruction." *Building Back Better: Delivering
798 People-centred Housing Reconstruction at Scale*, T. Schilderman and M. Lyons, eds., Practical
799 Action Publishing Ltd, Rugby, UK, 7–38.

800 Schilderman, T. (2014). "Introduction: What do we really know about the impact of reconstruction?" *Still
801 Standing? Looking Back at Reconstruction and Disaster Risk Reduction in Housing*, T.
802 Schilderman and E. Parker, eds., Practical Action Publishing Ltd, Rugby, UK, 1–19.

803 Shanmugasundaram, J., Arunachalam, S., Gomathinayagam, S., Lakshmanan, N., and Harikrishna, P.
804 (2000). "Cyclone damage to buildings and structures — a case study." *Journal of Wind Engineering
805 and Industrial Aerodynamics*, 84(3), 369–380.

806 Shelter Cluster. (2014). *Final Analysis of Shelter Recovery*. Global Shelter Cluster, Geneva.

807 Simpson Strong-Tie. (2019). *Wood Construction Connectors 2019-2020*. Simpson Strong-Tie, Pleasanton,
808 CA.

809 Stephenson, V., Finlayson, A., and Miranda, L. M. (2018). "A Risk-Based Approach to Shelter Resilience
810 following Flood and Typhoon Damage in Rural Philippines." *Geosciences*, 8(2), 76.

811 Stewart, M. G., Ginger, J. D., Henderson, D. J., and Ryan, P. C. (2018). "Fragility and climate impact
812 assessment of contemporary housing roof sheeting failure due to extreme wind." *Engineering
813 Structures*, 171, 464–475.

814 Suaris, W., and Khan, M. S. (1995). "Residential Construction Failures Caused by Hurricane Andrew."
815 *Journal of Performance of Constructed Facilities*, 9(1), 24–33.

816 Talatala, F., Dimapilis, R., Bondad, E., and Eusebio, D. (2014). *Strength and Related Properties of Coconut
817 Lumber Samples Submitted*. Forest Products Research and Development Institute, Laguna,
818 Philippines.

819 Thurton, D. A. W., Sabnis, G., and Raval, P. (2012). "Performance of various semi-engineered roof deck
820 systems under high velocity winds." *Scientia Iranica*, 20(1), 34–43.

821 TPU. (2007). "TPU aerodynamic database of low-rise buildings." *Tokyo Polytechnic University (TPU),
822 Japan*, <<http://wind.arch.t-kougei.ac.jp/system/eng/contents/code/tpu>>.

823 Turnbull, M., Sterrett, C., Hirano, S., and Hilleboe, A. (2015). *Extending Impact: Factors Influencing
824 Households to Adopt Hazard-Resistant Construction Practices in Post-Disaster Setting*. Catholic
825 Relief Services, Baltimore, Maryland.

826 Twigg, J. (2017). *Self-recovery from Disasters: An Interdisciplinary Perspective*. Working Paper, Overseas
827 Development Institute, London.

828 UNISDR. (2015). *Sendai Framework for Disaster Risk Reduction 2015-2030*. United Nations Office for
829 Disaster Risk Reduction.

830 Unnikrishnan, V. U., and Barbato, M. (2017). "Multihazard Interaction Effects on the Performance of Low-
831 Rise Wood-Frame Housing in Hurricane-Prone Regions." *Journal of Structural Engineering*,
832 143(8), 4017076.

833 Wolfe, R. W. (1983). *Contribution of Gypsum Wall Board to Racking Resistance of Light-frame Walls*.
834 U.S. Department of Agriculture, Forest Service, Forest Products Laboratory.
835

836 **Figure Captions**

837 **Fig 1.** Examples of NGO or government housing designs constructed following Yolanda: a) Bangon, b)
838 Sagasumbut-Duplex, c) San Pablo, d) Candulo, and e) Sohoton-Plywood

839 **Fig 2.** Examples of wall racking in Typhoon Ursula in houses constructed after Yolanda in Candulo, note
840 the image on the right is a complete soft-story failure.

841 **Fig 3.** Schematic of typical roof and wall structures for the studied houses: a) section view of the panels,
842 purlins, truss, and connections for any truss in a gable roof and common truss in a hip roof; b) elevation
843 of a wooden wall frame with a knee brace.

844 **Fig 4.** Overview of the analysis process.

845 **Fig 5.** Examples of roof connections using a) wooden cleats and b) hurricane straps

846 **Fig 6.** Probabilities of failure onset in wall framing (structural integrity performance level), roof panels
847 (continued occupancy performance level), and roof-to-wall connections (life safety performance level) for
848 the Candulo house design as a function of wind speed (3-second gust). The vertical lines represent the
849 maximum 3-sec gusts estimated for Candulo in three recent storms. [1kph = 0.62 mph].

850 **Fig 7.** Summary of median wind speeds (3-sec gusts) of onset failures in wall frames (structural integrity
851 performance level), panels (continued occupancy performance level), and roof-to-wall connections (life
852 safety performance level) for each housing type. Vertical lines indicate the maximum 3-sec wind gusts
853 measured in three recent storms [1 kph = 0.62 mph].

854 **Fig 8.** Sensitivity analysis results for variations of a) purlin-to-truss connections, b) roof-to-wall
855 connections, and CGI-fastener interface properties: c) panel thickness, d) fastener spacing, e) panel

856 thickness and fastener spacing, and f) purlin spacing. GA = gauge and 150/150 = fastener spacings on
857 edge/interior purlin lines. [1 kph = 0.62 mph].

858 **Table 1.** Design details of studied houses

Design Name	Location	# of Houses	# of Stories	Height (m)	Plan Dimensions (m x m)	Column Material	Wall Material	Roof Shape (# of trusses) ^d	Roof-to-Wall Connection	Purlin-to-Truss Connection	Purlin Spacing (mm)	Panel Fastener (Spacing)
Bangon	Leyte	150 ^a	1	3.4	6.45 x 4	Reinforced concrete	Masonry/plywood	Gable (4)	Wrapped rebar	Wooden cleats	575	Umbrella nails (150/300)
Candulo	Eastern Samar	105 ^a	1	4.35	6 x 3	Coconut lumber	Amakan	Hip (3,6)	Hurricane straps	Hurricane straps	600	Umbrella nails (150/150)
Caputian-Amakan	Eastern Samar	119 ^b	1	3.95	5.5 x 3.6	Coconut lumber	Amakan	Hip (2,4)	Wooden cleats	Hurricane straps	525	Umbrella nails (150/300)
Caputian-Masonry	Eastern Samar	119 ^b	1	3.75	4 x 3	Reinforced concrete	Masonry	Hip (3,6)	Wooden cleats	Wooden cleats	625	Umbrella nails (150/300)
Linao	Leyte	1000 ^a	Loftable ^c	5.2	6.5 x 4	N/A	Concrete	Gable	Bolted	N/A	650	J-bolts (300/300)
Sagasumbut -1Story	Leyte		1	3.15	4.5 x 3.65	Lumber	Plywood	Hip (3,6)	Toe-nailed & hurricane straps	Hurricane straps	650	Umbrella nails (150/300)
Sagasumbut -2Story	Leyte	484 total	2	6.5	3.65 x 2.45	Lumber	Plywood	Hip (3,6)	Toe-nailed & hurricane straps	Hurricane straps	850	Umbrella nails (150/300)
Sagasumbut -Duplex	Leyte		2	6.5	4.9 x 3.65	Lumber	Plywood	Hip (3,6)	Toe-nailed & hurricane straps	Hurricane straps	850	Umbrella nails (150/300)
San Pablo	Leyte	42	2	6.55	4 x 3.5	Coconut lumber	Plywood/amakan	Gable (3)	Toe-nailed	Hurricane straps	400	Screws (150/150)
Sohoton-Amakan	Eastern Samar		1	3.45	4 x 4	Coconut lumber	Amakan	Gable (3)	Bolted	Wooden cleats	450	Umbrella nails (150/300)
Sohoton-Plywood	Eastern Samar	63 total	1	5.8	5 x 3.5	Coconut lumber	Amakan	Gable (3)	Bolted	Wooden cleats	450	Umbrella nails (150/300)
Tolosa	Leyte	558 ^a	Loftable ^c	5.5	5.25 x 4	N/A	Masonry	Gable	Bolted	N/A	600	Screws (150/300)

859 ^aThis same housing design was also used in other communities. This number includes those only in the studied community.860 ^bTotal number expected to be built. Some houses were still under construction or waiting to be built as of January 2020.861 ^cHouse was built with 1-story with space to add interior second floor. ^dFirst number is the number of main trusses and second number is number of hip trusses.

862 **Table 2.** Performance levels and their corresponding failure modes and component-specific failure
 863 mechanisms

Performance Level ^a	Associated Failure Mode	Component-Specific Failure Mechanism
Continued Occupancy	Loss of 1 st roof panel	Failure of the CGI-fastener interface CGI-fastener interface (Fastener pullout or CGI tear-out) for 10% of a panel's fasteners OR Failure of all the purlin-to-truss connections for a purlin at the edge of the roof
Life Safety	Roof system failure	Failure of one roof-to-wall connection
Structural Integrity	Wall failure	Wall racking of one wall

864 ^a As defined in van de Lindt and Dao (2009)

865 **Table 3.** Uncertainty parameters for wind load and resistance capacities

Source of Uncertainty	Distribution	COV	Source
Wind load on component	Normal	0.2	(Li and Ellingwood 2006)
Fastener pullout	Normal	0.25 ^b	(Li and Ellingwood 2006; Stewart et al. 2018)
CGI tear-out	Normal	0.25 ^b	(Stewart et al. 2018)
Hurricane straps	Normal	0.1	(Ellingwood et al. 2004; Li and Ellingwood 2006)
Wooden cleat connection	Normal	0.4	Assumed ^a
Toe-nailed connection	Normal	0.3	(Cheng 2004; Morrison and Kopp 2011)
Bolted connection	Normal	0.4	Assumed ^a
Racking resistance	Normal	0.4	Assumed ^a

867 ^a We assumed a COV of 0.4 for capacities that were calculated from equations or extrapolated from similar tests. As
 868 values were not drawn from experimental tests, we assumed a higher level of uncertainty than for values that have
 869 been validated through repeated testing.

870 ^b COV for fastener pullout/CGI tear-out also incorporates variance in capacity based on improperly installed fasteners.

871 **Table 4.** Design variations considered in sensitivity analysis

Component	Variations Considered		
CGI thickness	24-gauge ^a	26-gauge	28-gauge
Fastener spacing	As-built	150mm/150mm (6in/6in)	150mm/300mm (6in/12in)
Purlin-to-truss connection	Wooden cleats	Hurricane straps	
Roof-to-wall connection	Wooden cleats	Toe-nailed	Hurricane straps
Purlin spacing	600 mm	450 mm	300 mm
Eave length	0 m (no eave)	0.5 m	1 m

872 Note: The first number in the fastener spacings indicates the spacing on the edge of the panel, and the second refers
 873 to the spacing along purlin lines on the interior of the panel.

874 ^a Gauge thickness increases as the number increases. 24-gauge is the thickest panel considered.

875
 876
 877
 878
 879
 880
 881
 882
 883
 884
 885
 886

887 **Table 5.** Median wind speed (3-sec gust) causing onset of failure in different components for the studied
 888 houses [1 kph = 0.62 mph]. Bolded values indicate the median wind speed of governing failure mode.

	1 st panel failure (CGI-Fastener) (kph)	1 st panel failure (Purlin-to-Truss) (kph)	Roof-to- wall failure (kph)	Wall failure (kph)	Expected failure mechanism based on first failure
Bangon	187	133	N/A	N/A	Panel failure due to purlin-to-truss connection
Candulo	223	371	259	161	Wall racking
Caputian-Amakan	306	360	227	190	Wall racking
Caputian-Masonry	284	252	N/A	N/A	Panel failure due to purlin-to-truss connection
Linao	148	N/A	317	N/A	Panel failure due to fasteners
Sagasumbut-1Story	234	371	270	280	Panel failure due to fasteners
Sagasumbut-2Story	212	274	302	199	Wall racking
Sagasumbut-Duplex	191	353	266	252	Panel failure due to fasteners
San Pablo	288	176	180	191	Panel failure due to purlin-to-truss connections
Sohoton-Amakan	283	180	342	240	Panel failure due to purlin-to-truss connection
Sohoton-Plywood	283	155	342	203	Panel failure due to purlin-to-truss connection
Tolosa	208	N/A	333	N/A	Panel failure due to fasteners

889